

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002532227
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	DAVIS, F. B.
8. Well No.	2
9. Pool Name or Wildcat	TEAGUE GLORIETA-UPPER PADDOCK, SOUTHWEST
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR=3323

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>A</u> : <u>510</u> Feet From The <u>N</u> Line and <u>500</u> Feet From The <u>E</u> Line Section <u>8</u> Township <u>23S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR=3323

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-09-98: MIRU. PULL RDS & PMP. INSTL BOP.
2-10-98: TAG BTM @ 5359' (PBTD). OK. WELL CHECK TBG OUT OF HLE.
2-11-98: TIH W/SONIC HAMMER ON TBG. WSH GLORIETA-PADDOCK CSG PERFS 5120-5290' W/2000 GALS 15% NEFE HCL. MAX TBG PRESS-2050#. MAX CSG PRESS-920#. AIR-4 BPM. ISIP-700#. 5 MIN-VAC. TIH W/5300'-OPEN SONIC TOOL. RU SWAB. START FL @ 1500'. SWAB & RECVD 116 BLW, TRACE OF OIL. END FL @ 4200'.
2-12-98: TIH W/PURGE VALVE, IPC JT, TBG. MUD ANCHOR @ 5334.05'. SN @ 5306.30, TAC @ 5111.88'. NDBOP. NUWH. TIH W/GAS ANCHOR, PUMP & RDS. LOAD & TEST TO 500#-OK. SPACE OUT 6". HUNG ON. PUMPING @ 6:00 PM.
2-13-98: TIH W/LONGER PUMP. RAN SAME RODS COFIGURATION. SPACE OUT 3" OFF BTM. HITTING BTM SLIGHTLY. RDMO. PUMPING & TESTING.
3-09-98: ON 24 HR OPT. PUMPED 66 BO, 45 BW, & 10 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 3/10/98
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

ORIGINAL SIGNED BY C. W. WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

