

YATES PETROLEUM CORPORATION
Haracz AMO Federal #7
Section 19-T24S-R32E
Lea County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 8238-8280': TIMES: TO 20"; SI 61"; TO 90"; SI 180". RECOVERY: 155' of heavy oil and gas cut mud, 70' water and 5073' gas in drill pipe. SAMPLER: 1.16 cfg and 500 cc water. PRESSURES: IHP 3806; IFP 91-91; ISIP 755; 2nd FP 120-125; FSIP 1740; FHP 3806

DST #2 8288-8338' (Brushy Canyon): TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 60". RECOVERY: trace oil, 90' of mud and 257' of formation water. SAMPLER: .03 cfg, 2550 cc water. PRESSURES: IHP 3791; IFP 66-80; ISIP 2910; 2nd FP 104-150; 2nd SIP 3126; FFP 167-211; FHP 3793

DST #3 9586-9752' (1st Bone Springs Sand): TIMES: TO 20"; SI 60"; TO 240". RECOVERY: 112' of mud and 265' of water. SAMPLER: .03 cfg, 2550 cc water. PRESSURES: IHP 4397; IFP 111-100; ISIP 627; FFP 105-221; FHP 4398