Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

NM Oil 1980

FORM APPROVED Budget Bureau No. 1004-0135

BUREAU DE LA	IND MANAGEMENT LICH NM 60	241
	Hob NM 60	5. Lease Designation and Serial No.
SUNDRY NOTICES AND	REPORTS ON WELLS	NMLC - 030187
Do not use this form for proposals to drill or d		6. If Indian, Allottee or Tribe Name
	OR PERMIT-" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of well X Oil Gas Other		8. Well Name and No.
2. Name of Operator		C. E. Lamunyon #63
ARCH PETROLEUM, INC.		9. API Well No.
3. Address and Telephone No.		30-025- 3346D
10 Desta Dr. Suite 420E, Midland, TX 79705 (915) 685-1961		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		TEAGUE BLINEBRY
Unit F, 1420' FNL, 1340' FWL, Sec. 27, T23S, R37E(new hole)		11. County or Parish, State
Unit F, 1400' FNL, 1340' FWL, Sec. 27, T23S, R37E(old hole)		LEA COUNTY, NM
CHECK APPROPRIATE BO	X(S) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA
12 TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
<u></u> -	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
<u></u> -	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other Skid rig & spud new hole	Dispose Water (Note: Report results of multiple completion on Well
Charting (Clark stop all partinent de	ails, and give pertinent dates, including estimate date of starting any proposed wo	Campletion or Recompletion Report and Log form.) ork. If well is directionally drilled.
Pulled 100,000# and parted casing. F Attempted to fish casing. Worked fish Left 9 jts casing in hole from 394'-762 Do to high cost of recovering stuck pip 1. Plug and abandon existing hole per Set cement plug from 705'-1005' Set cement plug from surface to 4 Cement will be Class "C" neat 2. Skid drilling rig 20' South of origin 1420 from North line \$ 1340' from Section 27, T23S, R37E(unit F) See survey plat attached	8-5/8", 20#, X-42 CSG. Stuck casing at 891 Recovered 11 jts. In up hole 129' and stuck again. 2' pe. The following plan is submitted for your appearance of the stuck casing) 44'(50' into stuck casing) The Re spud well. New location will be: 3 m West line.	RECE TH JUL 24 TOSWELL BUR BUR
14. I hereby certify that the forgoing is true and correct	given on 11-1	7/02/07
Signed Illum Curry	Title Geologist	Date //23/97
(This space for Federal or State office use) Approved by (ORIG. SGD.) ARMANDO A. LOPEZ Conditions of approval, if any:	Title_PETROLEUM ENGINEER	Date 8/5/97