

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

District I
P.O. Box 1980, Hobbs, NM 88240

District II
P.O. Drawer DD, Artesia, NM 88210

District III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-34687
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG 6337
7. Lease Name or Unit Agreement Name JACKSON UNIT
8. Well No. 7
9. Pool name or Wildcat Johnson Ranch Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator MURCHISON OIL & GAS, INC.	
3. Address of Operator 1445 ROSS AVE., LB 152, DALLAS, TX. 75202-2883	
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>15</u> Township <u>24S</u> Range <u>33E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 12-3/4" hole to 5275'. Ran 133 joints of 9-5/8", 47 #/ft. S-95 (123 joints) and P110 (15 joints) LTC to 5275'. Cemented w/1610 SXS interfill "C" neat followed w/275 SXS PP 2% CaCl. Circulated 110 SX to pit bump plug. Plug & float held. WOC 18 hrs. Test pipe rams & casing to 1500 PSI. Held ok. Drill out shoe with 8-1/2" bit and return to drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Michael S. Daugherty

TITLE

VICE PRESIDENT OPERATIONS

DATE

11/9/99

TYPE OR PRINT NAME

MICHAEL S. DAUGHERTY

(214) 953-1414

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT SUPERVISOR

NOV 24 1999

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

3
C