| Dec. 1973 | | Budget Bureau No. 42-R142 |
|-------------------------------|--|---|
| | UNITED STA. J | 5. LEASE |
| | DEPARTMENT OF THE INTERIOR | IC-061936 A |
| | GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| CHNDDY | NOTICES AND DEDODES ON WELLS | 7. UNIT AGREEMENT NAME |
| | NOTICES AND REPORTS ON WELLS | Cotton Draw Unit |
| reservoir. Use Form | m for proposals to drill or to deepen or plug back to a different 9-331-C for such proposals.) | 8. FARM OR LEASE NAME |
| 1 011 | | Cotton Draw Unit |
| 1. oil 😾 | gas other | 9. WELL NO. |
| 2. NAME OF O | DEDATOR | 19 |
| | aco Inc. | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS O | | Paduca Delaware |
| | | |
| | x 728, Hobbs, New Mexico 88240 | AREA |
| below.) | F WELL (REPORT LOCATION CLEARLY. See space 17 | Sec. 10, T-25-S, R-32-E |
| AT SURFACE | ::660' FSL & 1980' FWL | 12. COUNTY OR PARISH 13. STATE |
| | DD. INTERVAL: (Unit Letter 'N') | Lea New Mexico |
| AT TOTAL D | | 14. API NO. |
| 16 CHECK APP | ROPRIATE BOX TO INDICATE NATURE OF NOTICE, | 14. API NO. |
| | R OTHER DATA | 15 SI SVATIONO (OLIONA DE LADE AND |
| METOWN, ON | OTTER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WI |
| REQUEST FOR A | APPROVAL TO: SUBSEQUENT REPORT OF: | 3+37 (Dr) |
| TEST WATER SH | | |
| FRACTURE TREA | | in the second of the second |
| SHOOT OR ACID | | VEIII |
| REPAIR WELL | | (NOTE: Report results of multiple completion or zo |
| PULL OR ALTER | | 1979 change on Form 9–330.) |
| MULTIPLE COMP CHANGE ZONES | | |
| ABANDON* | 님 U. S. GEOLOGIC | CAL SURVEY |
| (other) Cl | ean out junk * HOBBS, NEW | MEXICO |
| | | |
| including est | PROPOSED OR COMPLETED OPERATIONS (Clearly stated timated date of starting any proposed work. If well is done true vertical depths for all markers and zones pertiner | directionally drilled, give subsurface locations as |
| | | |
| 1. | Rigged up. Install BOP. | |
| • | 1119800 ab. Till oatt Doi. | |
| 2. | Clean out to 4771'. | • |
| <i>د</i> • | Orcan odo oo ijir . | |
| 3. | Install production equipment. test ending 2-12-79, well pump water, GOR 1280. | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Subsurface Safet | y Valve: Manu. and Type | Set @ I |
| 18 I hereby certi | ify that the foregoing is true and correct | |
|) /J | | 0.36.80 |
| SIGNED 1 | Company TITLE Asst. Dist. St | upt. DATE 2-16-79 |
| | (This space for Federal or State off | fice use) |

•

____ TITLE ____

FEB 20 1979

S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO