Form 9-881 a. (Feb. 1951)

_____X

(SUBMIT IN TRIPLICATE) UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY Budget Bureau No. 42-R358.4. Approval expires 12-31-60. Land Office LAS Cruces. Lease No. LC-061936A.... Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO ABANDON WELL	TURE OF REPORT, NOTICE, OR OTHER DATA)
Well No2 is located 1980 ft. from	Itdland, Texas, January 17, 19.61 [NX] [N] [S] line and 1980. ft. from [W] [W] [W]
NE L. SW L. Sec. 10 T-25-S R-32 (4 Bec. and Bec. No.) Paduca-Delaware (Field)	PE NMPM (Meridian)

The elevation of the derrick floor above sea level is 3450... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD - 323'

Spudded 9 7/8" hole 1:30 P.M. January 14, 1961 Ran 311' of 7 5/8" O.D. casing, 24:00 lb, H-40, 8-R, and cemented at 323' with 250 sx. regular. Plug at 300'. Cement circulated. Job complete 8:00 P.M. January 14, 1961.

Tested 7 5/8" 0.D. casing for 30 minutes with 1000 PSI from 8:00 to 8:30 P.M. January 15, 1961. Tested o.k. Drilled cement plug and re-tested for 30 minutes with 1000 PSI from 10:30 to 11:00 P.M. January 15, 1961. Tested o.k. Job complete 11:00 P.M. January 15, 1961.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____TEXACO_Inc.

Address P. O. Box 352

Midland, Texas

By M. B. Hundhard

Title Assistant District Superintend-GPO 918 507 ent