Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.	M_C	116	Ç	() !	Ŋ	\$.	COM	쳈	¢	5	10
					^	10	۸					

P.C 54 1940

HORAC WEST TOP FORM APPROVED

Budget Bureau No. 1004-0135						
Expires: March 31, 1993						

SUNDRY NOTICES AND REPORTS ON WELLS	5. Lease Designation and Serial No. LC 062300					
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals	6. If Indian, Alottee or Tribe Name					
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation					
Type of Well: OIL GAS OTHER	8. Well Name and Number COTTON DRAW UNIT					
P. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	48					
Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0426	9. API Well No. 3002508220					
Unit Letter L: 2310 Feet From The SOUTH Line and 330 Feet From The	10. Field and Pool, Exploaratory Area PADUCA DELAWARE					
WEST Line Section 22 Township 25S Range 32E	11. County or Parish, State LEA , NEW MEXICO					
2. Check Appropriate Boy(s) To Indicate Nature of Notice Re						
Check Appropriate Box(3) To indicate Nature of Notice, No	PE OF ACTION					
Abandonment	Change of Plans					
Recompletion	New Construction					
Notice of Intent Plugging Back	Non-Routine Fracturing					
Subsequent Report Casing Repair	Water Shut-Off					
Final Abandonment Notice Altering Casing OTHER: EXTEND TA STATU	Conversion to Injection S Dispose Water					
Z OTHER ZALERO IX OTATO	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)					
work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all Texaco Exploration and Production Inc. respectfully submits it's plans concerning notice 0162 (067A). Texaco requests an extended TA status for the above well. The following procedure to test casing and plug will be performed and a subsequent 3160-5 will be submitted requesting official TA status. 1. Notify BLM 24 hours in advance of work. 2. Test casing and plug with 500 psi for 30 min. 3. Classify well to TA status. TEPI will submit pressure chart and subsequent report requesting Temporarily Abandonment Status on this well.						
14. I hereby certify that the foregoing is true dispersed. SIGNATURE: TYPE OR PRINT NAME Dayrell J. Carriger	DATE 10/27/94					
APPROVED BY (ORIG. SGD.) JOE G. LARA TITLE PETROLEUM ENG	DATE ///30/94					
CONDITIONS OF APPROVAL, IF ANY: See attached. Test to be per Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unite	d States any false, fictitious or fraudulent statements of					
representations as to any matter within its jurisdiction.						

RECEIVED

OFFICE OFFICE