## APPRILLED TO A STORAGE WATER THE

APPRO D	3-2-6 1 2 3 3 2 6 1 2 2 3 3 2 6 1 2 2 3 2 3 4 1 2 2 2 3 3 2 3 4 1 2 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
Form 9-861 a MAY 17 1961 HOB	Budget Bureau No. 42-R368.4. Approval expires 12-31-60.
J. GORDON (SUBMIT)	IN TRIPLICATE) Land Office New Mexico
ACTING DISTRICT ENGINEERUNITE	D STATES Less No. LC 064727
0 GEOLOG	ICAL SURVEY
	And the second of the second o
SUNDRY NOTICES AN	ID REPORTS ON WELL 1982
NOTICE OF INTENTION TO DRILL	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.	SUBSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTERCEPT OF PULL OR ALTER CASING.	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHECK MARK WA	FURE OF REPORT, NOTICE, OR OTHER DATA)
SW/1, Sec. 33 25S 32 (b) Sec. and Sec. No.) (Twp.) (Range of Sub-  Unde signsted (County or Sub-  (County or Sub-  The elevation of the derrick floor above sea level in DETAILS  (State names of and expected depths to objective sands; show since, we imposints, and all other in the state of t	line and 660 ft. from W line of sec. 33  E
12/14/60 Ran 327 8-5/8" casing - C	ement circulated Inspected 5-11-61
12/24/60 T.D. 4663' - No Commercial	oil or gas found OK- for abdurk
12/24/60 Cement plugs 10 sks @ ground level 20 sks @ 344 Bottom of sur 20 sks @ 1050 Top of Rustl - 20 sks @ 1440 Bottom of Ru 20 sks @ 3050 Top of Salt 25 sks @ 4550 Top of Delay Hole full of mud laden mate	rface casing ler ustler ware sand
Company HILL & MERKER	s - , the Geological Survey before operations may be commenced.
Address 519 Midland Savings &	/
Loan Bldg	All a

30-025-08240

Title Fred Olk.

GPG 862040

Midland, Texas