



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **LC 068846**
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|--|--|---|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | X |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 21, 1961

Well No. **1** is located **1980** ft. from **N** line and **660** ft. from **E** line of sec. **8**

SE/4 Sec. 8
(1/4 Sec. and Sec. No.)

T-25-S R-33-E
(Twp.) (Range)

(Meridian)

Wildcat
(Field)

Lee County
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **3456** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Surface csg. 8 5/8 @ 407'
Plugs: 15' @ surface
50' @ 390' - 440'
100' @ 1050' - 1150'
100' @ 1430' - 1530'
100' @ 4720' - 4820'
100' @ 5000' - 5100'

Location ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Santana Petroleum Corp.**

Address **Box 1205**
Midland, Texas

By *Ralph H. Hannon*
Title **Geologist**