


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 661400  
Unit Board

SUNDRY NOTICES AND REPORTS ON WELLS



NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**McCormick Lease**

**2-8**

19 **49**

Well No. **1** is located **660** ft. from **N** line and **659** ft. from **E** line of sec. \_\_\_\_\_

**22-4 22-4 18**  
(1/4 Sec. and Sec. No.)

**25-8**  
(Twp.)

**35-2**  
(Range)

**N.E.P.M.**  
(Meridian)

**Wildcat**

**Leon**

**New Mexico**

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is **3376** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 8 joints, 320', 1 1/2" OD Armo Spiral Weld casing, set at 336.75'. Cemented with 300 sacks. Pumped plug to 323'. Cement circulated to surface. Set 24 hours. Tested casing with 500' for 30 minutes before and after drilling plug. Test OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Phillips Petroleum Company**

Address **Box 1605**  
**Hobbs, New Mexico**

By *W. E. Clouston*  
District Chief Clerk

