



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

1950 APR 17 AM 10 16

Land Office **Las Cruces**  
Lease No. **032582 a**  
Unit **WPU**

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<b>Subsequent Report of Shut-Off Water and Pres</b>	<b>X</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Wells A-1**

**April 16**, 19 **59**

Well No. **1** is located **660** ft. from **S** line and **330** ft. from **W** line of sec. **1**  
**34/4 Sec. 1** **25** **36** **WPM**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Jalnet** **Lon** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3226** ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

**BEFORE WORKOVER - TO 3467' Line, PB 3150', DF 10', Elev. 3226' DF. Pay Yates 3070-83'. Csg. Ft. 5 1/2" at 3465'. Perfs. 3070-83'. TSD oil well prior to workover.**

**WORK DONE - Set cement retainer at 3064'. Spaced Yates 3070-83' w/100 Sk. San Spectra Log. Perf'd. Yates 3012-18', 3026-30', and 3034-46' w/4 JUPF. Attempted to free w/10,000 Gals. crude, 10,000# sand, and 150# AMMONITE. Screened out after 7,000 Gals. injected. Cleaned out sand. Failed to recover lead oil.**

**AFTER WORKOVER - TO 3467' Line, PB 3064'. Pay Yates 3012-46'. Perfs. 3012-18', 3026-30', and 3034-46'. Workover unsuccessful. Well returned to former status as TSD oil well. Workover started 2-4-59, completed 2-10-59.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Company**

Address **P. O. Box 68**

**Barrio, New Mexico**

By \_\_\_\_\_

Title **District Superintendent**