

HUBBS OFFICE COPY

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau 43-2281
Approval expires 12-31-52.


Lead Office *San Antonio*

Lead No. *066286*

Unit *RECEIVED*

FEB 11 1959

U. S. GEOLOGICAL SURVEY
NEW MEXICO



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		
NOTICE TO PLUG & ABANDON		X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 10, 1959

Well No. 2 is located 760 ft. from [S] line and 1980 ft. from [W] line of sec. 3

SE SW Section 3 25 South, 36 East 114PM
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Lea County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3212 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-29-59 Sec OK (SE)

Plugging operations begun February 10, 1959

Plugs at: 3600-3700' w/18 sacks w/50-50 pos-mix,
3200-3300' w/30 sacks w/50-50 pos-mix,
1350-1450' w/30 sacks w/50-50 pos-mix,
200-250' w/5 sacks w/50-50 pos-mix
At surface w/5 sacks

6-8-59
Marker 3" not permanently
marked. (Painted E. P. Campbell
seat hole not filled
2 1/2" 8 5/8" casing @ 221' left in hole.

7-28-59 Same
letter written
7-30-59 JEB

Core cable on location will be cleaned and leveled in approximately one month.
Site evidently filled before drying out. still very soft. JEB

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company E. P. Campbell

Address 902 Lubbock National Bank Bldg.

Lubbock, Texas

By *[Signature]*

Title Geologist