

(SUBMIT IN TRIPLICATE)

Land Office **Las Cruces**

Lease No. **LC 032582 (b)**

Unit **A**

TRIPPLICATE

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 9, 19 **52**

Well No. **2** is located **990** ft. from **N** line and **990** ft. from **E** line of sec. **12**

NE 1/4 NE 1/4

(1/4 Sec. and Sec. No.)

25-S

(Twp.)

36-E

(Range)

N.M.P.M.

(Meridian)

Cooper-Jal

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **3170** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set and cemented 560' of 9-5/8", 25.40 lb. Armeso casing and cemented with 350 sacks, 3% gel. cement. Cement circulated to surface. Completed cementing at 10:30 A.M. on 6-8-52. Will test at 10:30 A.M. on 6-10-52.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Kan-Mex Corporation**

Address **1203 Dallas National Bank Bldg.**

Dallas, Texas

By **G. D. Simon**

Title **Petroleum Engineer**