

DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
N.A.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A		7. Unit Agreement Name	
2. Name of Operator Maralo, Inc.		8. Farm or Lease Name F. Hanagan	
3. Address of Operator P. O. Box 832, Midland, Texas 79702		9. Well No. 2	
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>25-S</u> RANGE <u>36-E</u> NMPM.		10. Field and Pool, or Wildcat Jalmat	
15. Elevation (Show whether DF, RT, GR, etc.) N.A.		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	Re-PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-1-80 Top of plug 10'. Drld. & cleaned out to 150'.
1-2-80 Drld & cleaned out to 165'.
1-3-80 Drld. & cleaned out boards & junk to 180'
1-4-80 Drld 2' 8 3/4" hole. Had bit problems POH
1-5-80 Circ out wood & wore cuttings. Lost circs. Mixed mud and lost circ. material. No returns
1-6-80 Mixed mud and lost circ. material. Got returns. Circ. hole clean. Drld. and cleaned out to 182'.
1-8-80 Drld. and cleaned out to 185'. Stopped going. POF. Ran 8" magnet. REc some steel cuttings & some steel wool. Rec. some junk and steel wool.
1-09-80 Drld and cleaned out to 196'. Quit going. POH. Went in hole w/wireline spear. Spudded spear down to 203' POH w/spear. Went in hole w/fishtail bit to 186'. Cleaned out to 197' POH.
1-10-80 Spudded thru bridge and went to 197'. Drld & cleaned out to 202'. POH and made two trips w/ 5 1/2" magnet. Rec. some small pieces of junk. Went in hole w/6" Concave mill. Drld and cleaned out to 247' POH.
1-11-80 Drld and cleaned out to 322'. Circ. hole clean.
1-12-80 Drld & cleaned out to 375'. POH.
1-13-80 Drld & cleaned out to 448'. POH
1-15-80 Went in hole w/6" concave mill to 448'. Drld. & cleaned out to 450'. POH. Went in hole w/6" prong grab to 450'. POH.

CONTINUED ON PAGE 2

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Brenda Coffman</u>	TITLE <u>Production Clerk</u>	DATE <u>6-18-81</u>
APPROVED BY <u>A. H. Statman</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JUN 22 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		