

DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# MEXICO OIL CONSERVATION COMMISSION

Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
N.A.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- P & A
Name of Operator		
Maralo, Inc. (Cities Service) (Empire Oil & Gas)		
Address of Operator		
P. O. Box 832, Midland, Texas 79702		
Location of Well		
UNIT LETTER	K	2310
FEET FROM THE South LINE AND 2310 FEET FROM		
West	13	25-S
THE LINE, SECTION TOWNSHIP RANGE 36-E NMPM.		

7. Unit Agreement Name
8. Farm or Lease Name
Lidley B
9. Well No.
2
10. Field and Pool, or Wildcat
Jalmat
15. Elevation (Show whether DF, RT, GR, etc.)
N.A.
12. County
Lea

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	Re-PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

## 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

1-11-80 8 hrs. trying to get back into csg. - had boards on top of csg. Got into csg & cleaned out to 290'.

1-12-80 Drld. wood & cement & fill out w/9 5/8" csg. Cleaned wood out of pump.

1-14-80 Drld. Redbed & wood

1-15-80 Drld out fill.

1-16-80 Drld w/7 7/8" bit to top of 7" csg. @ 1548'. Circ. hole. Cleaned out inside 7" csg.

1-20-80 RUPU

1-22-80 PU & went in hole w/94 jts. 2 3/8" tbg. to 2936. Pmpd 50 sx cmt. w/2% CaCl<sub>2</sub>. POOH WOC 4 hrs  
Went in hole & tagged TOC @ 2680. Pld. up to 1552. Pmpd 75 sx cmt. POOH

1-24-80 Tagged TOC @ 1410'. Pmpd 40 sx cmt w/2% CaCl<sub>2</sub>. Pld out of hole & lay down tbg. WOC 4 hrs.  
Went in hole and tagged TOC @ 1320'. Pld up to 1150' & pmpd 40 sx cmt. Pld out of hole  
laying down tbg. to 150' - 65 sx plug. Pld out of hole.

1-25-80 Went in hole & tagged TOC @ 48'. RD & moved off.

1-30-80 Set 10 sx plug in top.

All pits have been filled and location has been levelled and cleared of junk.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	Brenda Coffman	TITLE	Production Clerk	DATE	6-18-81
PROVED BY	W. L. Fentress	TITLE	OIL & GAS INSPECTOR	DATE	JUN 22 1981
CONDITIONS OF APPROVAL, IF ANY:					