



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 032581a

Unit RECEIVED

JUL 23 1959

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Subsequent Report of Perf &amp; Frac</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sholes A-13

July 22, 1959

Well No. 3 is located 660 ft. from N line and 660 ft. from E line of sec. 13

35/4 13 25 S 36 E 121/2 W  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Jalmat Lee New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

BEFORE WORKOVER - TD 3100' Lm, PB 2955', DF 10', DF elev 3156', csg pt 5 1/2" at 3097', pay Yates 2864-2950', perf 2864-90', 2899-2902', 2905-07', 2909-14', 2916-18', 2921-2927', 2929-31', 2938-50'. Del at 215 PSIG 17 MCF/D, SIP 269.2 PSIA. Daily allow 42 MCF.

WORK - Clean out to 2892'. Perf Yates 2783-2814', 2820-47' w/2 JSPP. Acidized 2783-2892' w/2000 gals.

AFTER WORKOVER - TD same, PB 2892', csg pt same, pay Yates 2783-2892'. Perf 2783-2814', 2820-47', 2864-90'. Well is now dead. Workover started 7-13-59, comp. 7-17-59.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 62, Durice, New Mexico

3/4 UNCS WAM Pan Am - Hobbs-2,  
Atlantic - Midland-2, Standard -  
Houston-1, Standard - Midland-1.

By \_\_\_\_\_

Title District Superintendent

APPROVED  
JAN 10 1964  
FBI - NEW YORK