FORM C-103

NEW MEXIC OIL CONSERVATION COMMISSIC

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	x		

Midland, Texas, November 19, 1935.

OIL CONSERVATION COMMISSION,

Santa Fe, New Mexico.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the_____

Humble Oil & Refining	ompany T.	Koonce	Well No	in the
Company or Operator	· · · ·	Lease		
N/2	of Sec14	, т. 25-South	, <u>R. 36-Bast</u>	, N. M. P. M.,
Jal	Field,Ie	a		County.
The datas of this most more of fo	away Massawhan	10th to Normhon	14th inclusion	

The dates of this work were as follows: <u>November 10th to November 14th</u>, inclusive. Notice of intention to do the work was **Exercise** submitted on Form C-102 on <u>September 24</u>, 1935 **19** and approval of the proposed plan was **Exercise** obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Pulled 3267' of 2" tubing. Plugged back from 3323' to 2850' with 85 sacks of Trinity Portland Cement. Shot 7" casing at 2200', 1600' and 1400'. Broke loose at 1400'. Recovered 1432' of 7" casing, leaving 1446' in hole. Could not pull 10^E casing left 482' in hole. Filled hole to 1250' with heavy mud laden fluid, plugged off 7" casing with 25 sacks of El Toro cement. Filled balance of hole to top with heavy mud laden fluid. Top of 10-3/4" casing and regulation marker cemented with 10 sacks of El Toro Cement.

Witnessed by	Name	Company	Title
Subscribed and swo	orn to before the this	I hereby swear or affirm that is true and correct	the information given above
day of	Nov. , 193	S Name	burg
Dato	Tilson alaru	Position <u>Division Sup</u> ¹ t	•
	Notary Public	Representing Humble 011 Com	& Refining Co.,
My Commission e	xpires 0 - / V	Address Box W, Midlen	
Remarks:			entil

Title

Name

17.000

and the second pro-

and the second second

化化化化化化化化化化化化化化化化化化化 中心化化化化化化化化化

. . .

na se en la companya de la constructiva de la constructiva de la construcción de la construcción de la constru La construcción de la construcción d

(a) and (b) and

A state of the sta

医骨髓膜 化合物 化化合物 化化合物 建制造 化化合物 化化合物 医二氏反应 化乙烯酸乙酯医酸乙酯

area 你这些我们不是你们的你们,我就能到了这些你了。你们你们不是不是你们的做了。