



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **030554 A**
Unit **W.T. Joyner**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF XXXXX
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico Sept. 2, 1955

Well No. **2** is located **1980** ft. from **N** line and **1980** ft. from **E** line of sec. **26**

NW/4 SE/4 Sec. 26
(1/4 Sec. and Sec. No.)

25S
(Twp.)

36E
(Range)

N.M.P.M.
(Meridian)

Cooper-Jal
(Field)

Lea
(County or similar division)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **7** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 8/27/1955. Drilled to 1355' in Anhydrite. Set 8-5/8" OD casing at 1355' and cemented with 450 sacks by Halliburton Process. Cement circulated to surface. Plug down 8:30 P.M. 8/30/1955. WOC 36 hours. Pressured up to 1000# on casing. Pressure held at 1000# for 20 minutes. Drilled out cement plug. Pressured up to 1000# and pressure held at 1000# for 20 minutes. Now drilling ahead.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Skelly Oil Company**

Address **Box 38**

Hobbs, New Mexico

By

Title **Dist. Supt.**