

SCOUT REPORT
NEW MEXICO
OIL CONSERVATION COMMISSION

Langley-Mattley

Company Uscor Drilling Co.
 Farm Name Russell Well No. 1
 Sec. 18 Twp. 24 Range 37 County Lea
 Feet from Line: N. 660 S. 660 E. W.
 Elevation 3503 Method
 Contractor
 Spudded 6-7-46 Completed 7-7-46

AMOUNT
CASING & CEMENTING RECORD

Size	Feet	Inches	Sax Cement
8 7/8"	1164		150
5 1/2"	3440		550

ACID RECORD
Gals.

TA	1330	TG
TX		TSA
TCA		TGI
BX	2815	TYo
TY		TAbo
TSR		TPenn
Top Pay	3470	TQ
		TOrd

SHOOTING RECORD

No. of Quarts	From	To
No. of Quarts	From	To
S/	S/	S/
S/	S/	S/
S/	S/	S/

TUBING RECORD

PACKER

Date		Date	
6-4-46	Bldg. derrick		
6-11	TD 1164 RB; Rigging	7-8	51 shot w/330 Q+3
6-18	Ø 2926 L		3471-3597
6-25	TD 3440 L; WOC	7-16	1PFLOW 108 BORD thru
	5 1/2"		13/16" tbg chrt on 2" tbg
7-2	TD 3597 L; Prep		@ 3580
	to snab; show		
	oil 3569-97		

ILLEGIBLE

[illegible][illegible]

100-443887-100

1. The first step is to identify the problem. In this case, the problem is that the system is not working properly.