EF

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	 SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	 SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	 SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	 SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	 SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	 SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	 	
	 	l

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

				Visit 1	, 195
Well l	No. 11 is	located 2312 ft. f	from $\left\{ egin{array}{c} N \\ \bullet \end{array} \right\}$ line	and 330 ft. from	$\left\{ \begin{array}{c} E \\ \end{array} \right\}$ line of sec.
15/4	Sec. 22		8-37-		
	(1/4 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Pow/	(Field) (County or Subdivision)		sion) (State of Territory)		

The elevation of the derrick floor above sea level is 3242 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

in 5-31-54 ran USC of 5-5/8" Caping set at a375". Commented in two stages, let stage with 375 seeks of got and 110 seeks need comment. And stage 190 seeks need comment. After 10 hours 600 tested caping size 1150 pet, before and after drilling plug. Test CR. Resumed drilling operations.

Stage coller was set at 1232'.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	Staplica (1) and Car Dynamy	
Address		
	Hobbie, him destico	By Kneph Renduckson
		Title