

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLIC
(Other instructions c
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-032-450(a)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Enoco Production Company

3. ADDRESS OF OPERATOR
Cox Rd, Hobbs, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
2310' FSL x 330' FEL Sec. 22 (Unit I. NE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3256' R.D.B.

7. UNIT AGREEMENT NAME
SOUTH MARTIN UNIT Fed

8. FARM OR LEASE NAME

9. WELL NO.
13

10. FIELD AND POOL, OR WILDCAT
FOWLER-UPPER Veso

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
22-24-37

12. COUNTY OR PARISH
LEA

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☒ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Pursuant to Form 9-331 submitted 7-14-71.
Perforations 5154-5394 were fraced w/
36000 gal gelled brine + 48000 # sand. in 3 stages.
500 gal 15% acid preceded each stage. Swabbed in
and evaluated.

Prear - Amp 29 BD+6 BW 24 hrs. BOR 8500
after - Flw 5 BD+11 BLW 24 hrs. TPF-1050. 1200 MCFGPD.

TD- 7856'
PBD- 5720'
5 1/2" CSA 7856'

18. I hereby certify that the foregoing is true and correct

SIGNED _____

TITLE AREA ENGINEER

DATE 7-26-71

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD

JUL 28 1971

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

044 U-10-14
1-6212
1-5052
1-6214
1-ATC
1-CORRO
1-CHADW
1-10-1000

RECEIVED

APR 2 1971

OIL CONSERVATION COMM.
WASH. D. C.