


Form 9-331a
(March 1942)

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 057509

Unit _____



DUPLICATE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, September 5, 1947

G. L. Erwin (b)
Well No. 1 is located 660 ft. from N line and 1980 ft. from E line of sec. 26
NW 1/4 NE 1/4 Sec. 26 24-S 37-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie Mattix Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3193 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth: 995' - Anhydrite

Set and cemented 979' of 9-5/8" casing at 991' with 100 sacks.
Completed at 11:30 P.M. 8-30-47.

Tested casing with 1000#. Tested O.K. Drilled cement plug.
Drilled to 1000'. Tested casing through rams 500#. Tested
O.K. Completed 12:30 A.M. 9-3-47.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270

Midland, Texas

By J. H. H. H.

Title Asst. Dist. Supt.