

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **057509**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	X	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

G. L. Irwin (b)

Midland, Texas, December 3, 1947

Well No. **2** is located **1980** ft. from **N** line and **1980** ft. from **E** line of sec. **26**

SW/4 NE/4

(1/4 Sec. and Sec. No.)

24-S

(Twp.)

37-E

(Range)

NMPM

(Meridian)

Langlie-Mettix

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **3183** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth: **195 - Red Beds**

Set and cemented **182'** of **13-3/8"** casing at **196'** with **150** sacks.
Cement circulated. Completed **12:15 PM. 12-2-47.**

Anticipate drilling plug and testing casing by pressure method
after **24** hours or at approximately **12:15 PM. 12-3-47.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Texas Company**

Address **Box 1270, Midland, Texas**

By

P. Holliman

Title

Dist. Supt.

CIN-DR ✓
USGS-NMOC-W/B