


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Las Cruces**

Lease No. **057509**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

G. L. Erwin (b)

Midland, Texas, December 12, 1947

Well No. **2** is located **1980** ft. from **[N]** line and **1980** ft. from **[E]** line of sec. **26**

**3W/4 NE/4**  
(1/4 Sec. and Sec. No.)

**24-8**  
(Twp.)

**37-E**  
(Range)

**NMPM**  
(Meridian)

**Langlie-Mattix**  
(Field)

**Lea**

(County or Subdivision)

**New Mexico**

(State or Territory)

The elevation of the derrick floor above sea level is **3183** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Total Depth 1000' - Anhydrite**

**Set and cemented 986' of 9-5/8" casing at 999' with 100 sacks.  
Completed at 8:45 PM 12-6-47.**

**Drilled cemented plug at 8:20 PM 12-10-47. Tested casing before  
and after drilling plug with 1000#. Tested OK.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Texas Company**

Address **Box 1270**

**Midland, Texas**

By

Title

**Dist. Supt.**

CIE-HY  
USGS-H240CC-W/B