

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 057509
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

G. L. Erwin (b) 41696 Midland, Texas March 2, 19 48

Well No. 2 is located 1980 ft. from N line and 1980 ft. from E line of sec. 26

37-NE 24-E 37-E RTM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie-Mattix Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3183 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD: 3475 Dolomite and Sand

13-3/8" casing cemented at 196 with 150 sacks. 8-5/8" casing cemented at 999' with 100 sacks. 7" casing cemented at 3261' with 130 sacks. Drilled with rotary to 3300'—cable tools to 3475'.

On 1-14-48 well swabbed 20 1/2 bbls. oil in 14 hours thru casing. Well was shot 1-16-48, 3370-3475 with 420 lbs. Du Pont EL 411 (American Glycerine Co.) after loading hole with oil and using 1 yard gravel tamp. After cleaning out to bottom and running 2" KUE tubing to 3470', well flowed 55 Bbls. oil 1st 11 hours, GOR 525 and 40 Bbls. oil last 10 hours, GOR 1040. Used 12/64" choke Gravity 40.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270

Midland, Texas

By [Signature]

Title Dist. Supt.