

(SUBMIT IN TRIPLICATE)

Land Office **Las Cruces**
Lease No. **057509**
Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT CHARGE	X	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

O. L. Erwin (b) 41696 **Midland, Texas, March 18**, 19**48**
Well No. **3** is located **660** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **26**
NE 1/4 NE 1/4 **24-S** **37-E** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie Mattix **Lee** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3171** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth: **3540: - Dolomite**

13-3/8" casing cemented at 196' with 225 sacks. 10-3/4" casing cemented at 935' with 100 sacks. 7" casing cemented at 3269' with 125 sacks. Drilled with Rotary to 3318'--Cable Tools to 3540'.

On 3-17-48 well swabbed 25 barrels oil in 20 hours.

We now desire to shoot with 800 quarts DuPont EL-411 (American Glycerine Company) from 3320-3524', hole to be loaded with oil using approximately 1 yard gravel tamp on top of shot and cushion on bottom.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Texas Company**
Address **Box 1270**
Midland, Texas
By **[Signature]**
Title **Dist. Supt.**

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **057509**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	XX
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, March 18, 1948

G. L. Erwin (b) 41696

Well No. **3** is located **660** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **26**

NE $\frac{1}{4}$ NE $\frac{1}{4}$ **24-S** **37-E** **NMPM**
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Langlie-Mattix **Lea** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3171** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth: **3318 - Lims**

Set and cemented 3257' (100 Jts) 7" casing at 3269' with 125 sacks.
Completed 3:30 PM 2-20-48.

Rotary Rig was moved off, cable tools moved in and plug tested by bailing method. Drilled plug 2-27-48. Tested OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Texas Company**

Address **Box 1270**
Midland, Texas

By *[Signature]*
Title **Dist. Supt.**