

Form 9-331a
(March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 057509

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|---|---|----------|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... | X |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF REDRILLING OR REPAIR..... | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... | |
| NOTICE OF INTENTION TO ABANDON WELL..... | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

G. L. Erwin (b) 41696

Midland, Texas 10-14-, 1948

Well No. 4 is located 1980 ft. from N line and 660 ft. from E line of sec. 26

341 N1/4 Sec. 26
(1/4 Sec. and Sec. No.)

T-24-S
(Twp.)

R-37-E
(Range)

N42°E
(Meridian)

Langlie-Mattix
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the ~~surface~~ ground above sea level is 3159 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD: 205-Red Rock

Set and cemented 201' 13-3/8" casing at 187' with 225 sacks.
Completed 9:30 AM, 10-12-48. Cement circulated.

Drilled cement plug at 2:30 AM, 10-14-48. Tested casing with
250# before and after. Tested O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270

Midland, Texas

By [Signature]

Title Dist. Supt.