

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 032592(b)
Unit 41682

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

C. C. Fristoe (b) NCT-2 Midland, Texas 2-3, 1950

Well No. 3 is located 660 ft. from N line and 660 ft. from E line of sec. 26

SE 1/4 Sec 26
(1/4 Sec. and Sec. No.)

24S
(Twp.)

37E
(Range)

N17W
(Meridian)

Langlie-Mattix
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3175 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD: 1110 - Anhydrite

Ran and cemented 1097' (37 Jts) 9-5/8" casing at 1110' w/700 sacks. Completed 7:30 A. M., 1-29-50. Cement circulated.

Drilled cement plug 7:30 A. M., 1-31-50. Tested casing with 975# before drilling. Dropped to 950# on 1 hour test. Encountered hard cement at 1035'. Drilled cement plug & 1' formation. Tested cement job w/1090#. Dropped to 1050# in 1 hour. Drilling proceeded.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270

Midland, Texas

By J. L. Davis

Title Dist. Supt.