Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below: REPORT ON BEGINNING DRILLING OPERA-REPORT ON REPAIRING WELL TIONS REPORT ON PULLING OR OTHERWISE REPORT ON RESULT OF SHOOTING OR CHEM ALTERING CASING ICAL TREATMENT OF WELL REPORT ON RESULT OF TEST OF CASING REPORT ON DEEPENING WELL SHUT-OFF REPORT ON RESULT OF PLUGGING OF WELL Well was out on Pump Х Big Spring, February Place OIL CONSERVATION COMMISSION. SANTA FE, NEW MEXICO. Gentlemen: Following is a report on the work done and the results obtained under the heading noted above at the..... Schermerhorn Oil Corp. Well No. 54 Woolworth Company or Operator of Sec. 28 , T. 24 S , R. 37 E , N. M. P. M., NW-SN-NE Lattix Lee January 23, 1948 The dates of this work were as follows: Notice of intention to do the work was (was not) submitted on Form C-102 on January 12 1943 and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED January 23, Well # 56 was put on the Pump Witnessed by Title Company I hereby swear or affirm that the information given above Subscribed and sworn before me this..... is true and correct. Name ... _____ day of ______, 19_____ Position Superintendent Representing Schermerhorn Oil Coro. Notary Public Company or Operator

Remarks:

My commission expires

Address Box 70, Big Spring,

Title