

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	X	REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

Jal, New Mex., May 2, 1939.

Place

Date

OIL CONSERVATION COMMISSION,
Santa Fe, New Mexico.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

Weier Drilling Company,

Little Woolworth

Well No. **3** in the _____

SW of SW Company or Operator

28

Lease

24 S

37 E

of Sec.

T.

R.

N. M. P. M.,

Jal

Lea

Field,

County.

March 29, 1939.


The dates of this work were as follows: _____

Notice of intention to do the work ~~was~~ [was not] submitted on Form C-102 on _____ 19____

and approval of the proposed plan was ~~was~~ [was not] obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

7" O D Seamless casing set and cemented with 150 sacks at 3240 feet using Halliburton process. Well stood from March 29th until April 2nd when plug was drilled and tested for shut off. Well was in good condition after test.



Witnessed by *Lisa Palyan*
Name

Plains Production Co.

Company

HOBB'S OFFICE
Field Foreman.
Title

Subscribed and sworn to before me this _____

2nd

May 1939

day of _____

, 19____

J. H. Bailey
Notary Public

My Commission expires *Nov 29, 1941*

I hereby swear or affirm that the information given above is true and correct.

Name *A. S. Weier*

President.

Position _____

Representing **Weier Drilling Company,**

Company or Operator

Address **Jal, New Mexico.**

Remarks:

Roy Yarbrough
Name
OIL & GAS INSPECTOR
Title

ALL CELLANOROUS REPORTS ON WELLS

[illegible]

Illustration courtesy of Robert R. Schindler, Jr.

[illegible]

1. The first step is to identify the problem.
 2. The second step is to define the problem.
 3. The third step is to analyze the problem.
 4. The fourth step is to develop a solution.
 5. The fifth step is to implement the solution.
 6. The sixth step is to evaluate the solution.
 7. The seventh step is to monitor the solution.
 8. The eighth step is to maintain the solution.
 9. The ninth step is to improve the solution.
 10. The tenth step is to document the solution.

1. The first of these is the fact that the Commission has not yet received any information from the Government of the United States regarding the results of its investigation of the activities of the American Friends Service Committee in the Philippines.

THE UNIVERSITY OF TEXAS AT ARLINGTON LIBRARY