NEW MEXICO OIL CONSERVATION COM...ISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

	conal instructions in the Rules and Regulations of the Commission report by checking below:	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	REPORT ON PULLING OR OTHERWISE ALTERING CASING REPORT ON DEEPENING WELL.	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		
REPORT ON RESULT OF PLUGGING OF WELL	Installed pumping equipment x	
Big Spring.	Texas March 2, 1942	
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico.	Place Date	
Company or Operator	woolworth Well No. 1 & 5 in the	
Field,Field,	, T. 24S , R. 37E , N. M. P. M., County	
The dates of this work were as follows:	Y 5th to 27th	
Notice of intention to do the work was (XXXXX) submit and approval of the proposed plan was (XXXXX) obtain		
DETAILED ACCOUNT OF WOR	K DONE AND RESULTS OBTAINED	
	ent has been installed on wells	
have been installed as yet.		

Witnessed by	0	
	Сотрану	Title
Subscribed and sworn to before me this	I hereby swear or affirm that the is true and correct	information given above
2nd day of March , 1942	Name JAPA	berto
Gene Harrington Notary Public	Position Superintende	nt
Gene harrington Notary Public	Representing Schermerhorn	
My Commission expires June 1, 1943	Address Box 70, Big Spr	
Remarks:	Roy	yerlineigh.
	======================================	Title