

Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office **Las Cruces**

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Lease No. **LC 032326-b**

Unit **NMPU**

PH 3:24

CORRECTED REPORT

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
Subsequent Report of Cleanout	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Jack B-30

JULY 31, 1958

Well No. **1** is located **1650** ft. from **[N]** line and **990** ft. from **[E]** line of sec. **30**

NK/4 Sec. 30
(1/4 Sec. and Sec. No.)

24S
(Twp.)

37E
(Range)

NMPM
(Meridian)

Jalmat
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **3265** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Before Workover: TD 3372' sand and lime, DF 10', elev 3265' DF. Pay Yates and Seven Rivers 2833-3372' open hole. Csp pt 2833'. Prior to workover, 1958 average daily production was 80% MCF gas.

Work Done: Cleaned out to TD. Ran GRAM log. Cleaned up and resumed flowing.

After Workover: TD and pay same as before. Calculated open flow potential 1005 MCFFPD. SIP 720 psia. Deliverability at 600 psig 445 MCFFPD, at 150 psig 980 MCFFPD. Workover started 5-27-58, completed and tested 6-16-58. Conoco W. I. 25%.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Company**

Address **Box 68**

Sunrise, New Mexico

By

Title **District Superintendent**