

HUMBLE OIL & REFINING COMPANY'S

John Williams #1

**NE 1/4 of Section 34, Twp 24-South, Range 37-East,
Mettix Area, Lea County, New Mexico.**

DEVIATION SURVEYS

Acid bottle test at 385'	Hole straight
Acid bottle test at 750'	Hole straight
Acid bottle test at 1000'	Hole straight
Acid Bottle test at 1250'	Hole straight
Acid bottle test at 1500'	Deviation 1 degree
Acid bottle test at 1750'	Deviation 1 degree
Acid bottle test at 2415'	Deviation 1 degree
Acid bottle test at 3000'	Hole straight

DRILL STEM TEST

None