

HEUBLE OIL & REFINING COMPANY'S

John Williams #2

**NW 1/4 of Section 34, Twp 34-South, Range 37-East,
Muttiz Area, Lea County, New Mexico.**

DEVIATION SURVEY

Acid bottle test at 500'	Hole straight
Acid bottle test at 750'	Hole straight
Acid bottle test at 1000'	Hole straight
Acid bottle test at 1250'	Hole straight
Acid bottle test at 1500'	Hole straight
Acid bottle test at 1750'	Hole straight
Acid bottle test at 2000'	Hole straight
Acid bottle test at 2250'	Deviation 1 degree
Acid bottle test at 2500'	Deviation 1 degree

DRILL STEM TESTS

None