

**HEUBLE OIL & REFINING COMPANYS
JOHN WILLIAMS JR**

**SW 1/4 of Section 34, Twp 24-South, Range 37-East of
Lea County, New Mexico.**

DEVIATION SURVEYS

**Acid bottle test at 500' Deviation 1/2 degree
Acid bottle test at 750' Hole straight
Acid bottle test at 1000' Hole straight
Acid bottle test at 1240' Deviation 1/2 degree
Acid bottle test at 1500' Deviation 1 degree
Acid bottle test at 1750' Deviation 1/2 degree
Acid bottle test at 2000' Deviation 1/2 degree
Acid bottle test at 2250' Deviation 1 degree
Acid bottle test at 2552' Deviation 1 degree**

DRILL STEM TEST

None