

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

REPORT ON BEGINNING DRILLING OPERATIONS	X	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			


Date _____

Following is a report on the work done and the results obtained under the heading noted above at the_____

The dates of this work were as follows: Nov. 29th. 1937.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Well was spudded on the 29th. Now drilling.



DUPLICATE

Witnessed by Mike Rallison Boyd-Frost, Inc.
Name Company Title

Subscribed and sworn to before me this 27

day of January, 1938

Peter Bish
Notary Public

My Commission expires May 17, 1941

I hereby swear or affirm that the information given above is true and correct.

Name ✓ J. H. Johnson

Position Partner and V.P.

Representing Plains Production Company.

Company or Operator
Jal, New Mex.

Address _____

Remarks:

Guy Shepard Name
Oil & Gas Inspector
Title

FEB 3 - 1968

