

Indian Agency.....


(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces**
Lease or permit No. **032592**

Allottee.....

Lease No.....

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

The Texas Company's
C. C. Fristoe (a)

Midland, Texas, November 22nd, 1939

Well No. _____ is located **660** ft. from **N** line and **660** ft. from **E** line of sec. **35**
NW 1/4 Sec. 35 T-24-S R-37-E N.M.P.M.

(1/4 Sec. and Sec. No.)
Langile

(Twp.)

Lea

(Range)

(Meridian)

New Mexico.

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is **3195** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T. D. 1295' - Salt and Anhydrite.

Set and cemented 1287' (60 fts) of 8-5/8" OD 28# LW Casing at 1295' with 100 sacks. Completed cementing at 7:30 PM - 11-18-39.

Drilled Plug at 6:00 AM - 11-22-39. Bailed hole dry and let stand for 1 hour. Tested OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Texas Company,**

Address **Box 1270,**

Midland, Texas.

By
Title **District Superintendent.**

OCC-Hobbs

