



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 022379 (2)
Unit UNITED OFFICE

1961 JUN 19 AM 5 44

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		Other	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 16, 19 61

Well No. 4 is located 1900 ft. from N line and 330 ft. from E line of sec. 1
25-4 1 25-E 37-E 20PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilburt Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3137 ft. DF

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 6/7/61 - TD 7910' Lims & Shale. DST #8 7600 - 7910' Open 1 hr. Wash blow, Rec'd 150' Drig. fluid, 2 pints free oil on top. 30-ESIP-414, 30-FSIP-317. FF 207-248.
- 6/8/61 - Drig. 7935' Sand & lime, Visc. 34, Wt. 9.1.
- 6/9/61 - Drig. 8137' Lims & Shale, Bit #43, Visc. 34, Wt. 8.9.
- 6/10/61 - Drig. 8264' Lims & sand.
- 6/11/61 - No report
- 6/12/61 - Drig. 8416' Lims and sdy. shale, Visc. 34, Wt. 9.
- 6/13/61 - Case #1 8480-8493' Rec'd 13' being 8' black shale w/sand and streaks of Dolo. 3' sand and 2' Free'd Dolo. little bit sandy with oil stains and oil breaking out of fractures in last foot. Case was not analyzed.
- 6/14/61 - TD 8304' Dolo. & Chert. Making trip -

CONTINUED ON NEXT PAGE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. C. WILLIAMSON

Address BOX 16, MEDLAND, TEXAS

By Mary E. Smyce
 Mary E. Smyce
 Asst. to Supt.
 Title _____