



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Lee Grove  
Lease No. 933579 (1)  
Unit 1

1941 JUN 14 11 51 AM

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Other</u> <u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 14, 19 41

Well No. 4 is located 1990 from N line and 130 ft. from E line of sec. 1  
19/4 (1/4 Sec. and Sec. No.) 25-2 (Twp.) 17-2 (Range) 100W (Meridian)  
Willamette (Field) Lee (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3137 ft. SW

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

CONTINUED FROM PAGE 1

6/13/61 - TD 8347' Hole. BWT 49 8491 - 8347 (34'), Open 1 hr. 15 mins., S.I. 20 mins.  
 Run'g. 300' Drig. fluid. PP 275 - 275, Hyd. P. 2075 - 2075. Tool was full  
 of cuttings - may not have been a good test.  
 6/16/61 - TD 8378' Hole. and some chart. Making trip.

*Sample Top 8660 / 1490'*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. C. WILLEBAND  
 Address Box 16  
MIDLAND, TEXAS  
 By Mary E. Smyke  
 Title Asst. to Sup't.