



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **032579 (e)**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	☒
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 21, 19 **61**

Well No. **5** is located **1730** ft. from **N** line and **330** ft. from **E** line of sec. **1**

NN/4 **1** **25-S** **37-E** **MM/4**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildest **Lee** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3140** ft. **BF**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 7/11/61 - TD 3154' Anhy. & Gyp - WOC - Ran 33 Jts. 9 5/8" 32# new csg. set at 1005' cemented W/250 sx reg. nest 87 gal plus 100 sx Long Star 42 gal and 22 Cal. Ghl. - Plug down 11:45 PM 7/10/61 - Cement DID NOT Circulate - Ran Temp. Survey - SEE ATTACHED CHARTS - T/Cement 150'. Yested W/1400 #'s 30 mins. - Held OK. WOC 30 hrs.
- 7/12/61 - Drld. out 8 AM - Drig. 3171' Anhy. & Gyp - Tot. 3/4 deg. at 3154'
- 7/13/61 - TD 3393' Sd. & Lime, Making Trip, Bit #8. Tot. 3/4 deg. at 3393'
- 7/14/61 - Drig. 3494' Sd. & Lime, Bit #10.
- 7/15/61 - Drig. 3703' Sd. & Lime
- 7/16/61 - Drig. 3919' Sd. & Lime, Bit #11, Tot. 1/4 deg. at 3720'
- 7/17/61 - Drig. 4158' Sd. & Lime, Bit #12
- 7/18/61 - Drig. 4423' Lime, Bit #13, Visc. 38, Wt. 9.5
- 7/19/61 - TD 4581' Lime, Making Trip
- 7/20/61 - Drig. 4715' Lime, Bit #16
- 7/21/61 - Drig. 4930' Lime, Bit #17, Tot. 1 deg. at 4820', Visc. 35, Wt. 9.5.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **J. C. WILLIAMSON**

Address **BOX 16**

MIDLAND, TEXAS

By *Mary E. Sawyer*
Mary E. Sawyer
Title **Asst. to Supt.**