



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 032579 (E)

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 5, 19 61

Well No. 6 is located 330 ft. from N line and 330 ft. from W line of sec. 1

<u>NW/4</u>	<u>1</u>	<u>25-S</u>	<u>37-E</u>	<u>NMPM</u>
(¼ Sec. and Sec. No.)		(Twp.)	(Range)	(Meridian)
<u>Wildcat</u>		<u>Lea</u>		<u>New Mexico</u>
(Field)		(County or Subdivision)		(State or Territory)

The elevation of the derrick floor above sea level is 3135 ft. Gr.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8/19/61 - # 2957' Lime, # W/Clear Wtr., Bit #5, Tot. 1 3/4 deg. at 2690'
8/20/61 - No report
8/21/61 - # 3517' Lime & Dolo. # W/Clear Wtr., Bit #7, Tot. 1 1/4 deg. at 3366'
8/22/61 - # 3746 Sdy. Lime, Bit #8, Tot. 1 deg. at 3600'
8/23/61 - # 4116' Sdy. lime, Bit #10, Tot. 2 1/4 deg. at 4060'
8/24/61 - # 4440' Sdy. Lime, Bit #11, Tot. 2 1/2 deg. at 4340'
8/25/61 - TD 4678' Lime, Making trip for new bit. Tot. 2 3/4 deg. at 4660'
8/26/61 - No Report
8/27/61 - No report
8/28/61 - # 5340' Lime, Dolo., Bit #17, # W/Brine Wtr., Wt. 9.2, Tot. 2 3/4 deg. at 5290'.
8/29/61 - # 5565' Lime, Tot. 2 deg. at 5448'.
8/30/61 - # 5688' Lime, Tot. 2 1/4 deg. at 5680'.
8/31/61 - # 5825' Lime, Tot. 2 1/4 deg. at 5825'.
9/1/61 - # 6076' Lime, Bit #21, Tot. 3 1/4 deg. at 5935'.
I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. C. WILLIAMSONAddress BOX 16MIDLAND, TEXASBy Mary E. Smyre
Mary E. Smyre
Title Asst. to Supt.