



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 032579 (2)

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	☒
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	☒
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 18, 1961

Well No. 6 is located 330 ft. from N line and 330 ft. from W line of sec. 1

W/4 1 25-S 37-E Range
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox Lea New Mexico
(Field) (County or Sub Division) (State or Territory)

The elevation of the derrick floor above sea level is 3135 ft. Gr.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 8/12/61 - Spudded at 9 PM 8/12/61 - drld. to 130' - Ran 5 Jts. of 13 3/8" csg. 8 rd. 400' new set at 130' com/W/125 sx. reg. 4% gel plus 2% CC. Plug down 6:30 AM 8/13/61 - Cement circulated. WOC 24 hrs. - Tested csg. W/10000' 30 min. - Held ok.
- 8/13/61 - TD 130' - Prep to drill out. T/Redbed 65'.
- 8/14/61 - Drlg. 406' Redbed - Drlg. W/wtr. Tot. 1/2 day. at 120'.
- 8/15/61 - Drlg. 1040' S. lt & Anhy. Bit #2, Drlg. W/Wtr., Tot. 1/4 day. at 780'.
- 8/16/61 - Drlg. 2030' Anhy., Bit #3, Tot. 2 1/4 day. at 2000'.
- 8/17/61 - TD 2245' Anhy. - WOC - Ran 74 Jts. of 9 5/8" csg. 320' set at 2245' Com/W/150 sx. Encore 4% gel plus 2% CC. Plug down 10:15 PM 8/16/61. WOC 24 hrs., Tested W/10000' 30 min., - Held OK.
- 8/18/61 - Drld. out at 11 PM 8/17/61 - Drlg. 2480' Anhy. & Salt. Tot. 2 3/4 day. at 2347', Bit #4, Drlg. W/Wtr.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. C. WILLIAMSON

Address BOX 16

MIDLAND, TEXAS

By Mary E. Sayre
Title Asst to Supt.