			Section 6. LOG OF HOLE
Depth in Feet +		Tł ss	
From	То	in et	Color and Type of Material untered
0	120		Caliche - sand
120	960		Red bed
··			
	1		
·····	+		
······································			
			3/86 KR
•			i S Elev         32.55         6.5           Depth to k         Trc         6.5           Elev of         K         Trc         6.5
			Elev of KTrc
			Loc. No.
			Loc. No Hydro. Survey Field Check
			Hydro. Sulveyrield Check
<u> </u>		-+	
			SOURCE OF ALTITUDE GIVEN
			interpolated from Topo. Sheet
			Determined by Inst. Leveling
		_	Other OCC
	+		
·			

Section 7. REMARKS AND ADDITIONAL INFORMATION

This log is an excerpt from Oil Conservation Commission file at Hobbs, New Mexico.

Location: 25.37.1.131344 1980 FNL - 330 FWL Owner: National Coop. RFG. Assoc. -- Westates Fed. #4 Casing: 13 3/8" - 234' Rotary tools

The undersigned hereby certifies that, to the best of his knowledge and belief, the foregoing is a true and correct record of the above described hole.

Driller