

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT TO DISTRICT
(Other instructions on
reverse side)

Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032579 (e)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Westates Federal

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

Justis Montoya, North

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 1, T-25-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

National Cooperative Refinery Association

3. ADDRESS OF OPERATOR

2215 Wilco Bldg., Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

SW/4 NW/4 Section 1, T-25-S, R-37-E

1620' FNL, 330' FWL of Section

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3134 RT

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Place shut-in well on pump.

☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Westates Federal No. 8 is completed in the Montoya (Perf 7070'-7288') and has been shut-in due to downhole mechanical trouble. Rods and pump have been run and the well has been placed back on production. On gas-oil ratio test 10-4-74, the well pumped 15 B0, 0 BW, in 24 hrs. GTSM.

18. I hereby certify that the foregoing is true and correct

SIGNED

B. J. Kinser

TITLE Dist. Prod. Supt.

DATE 10-4-74

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

OCT 11 1974

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO