



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office **Las Cruces**Lease No. **032579 (E)**

Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 19, 1962

Well No. **8** is located **1620** ft. from **N** line and **330** ft. from **E** line of sec. **1**  
**NW/4** **1** **25-S** **37-E** **NM**  
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**North Justis (Ellenburger)** **Lea** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3124** ft. **Gr.**

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 2/7/62 - Drlg. 7277' Lime, Bit #17  
2/8/62 - Drlg. 7411' Dolo. & Chert  
2/9/62 - Drlg. 7629' Dolo. & Lime w/Chert Stringers  
2/10/62 - Drlg. 7822' Lime & Sd., Tot. 3 deg. at 7770'  
2/11/62 - Drlg. 7938' Lime & Shale  
2/12/62 - TD 8050' Sd. - DST #1 8000 - 8050', Open 2 hrs., Gas to surf. 1 hr. 46 mins., Rec'd 110' Mud Cut Oil, 270' Highly Oil & Gas Cut Drlg. Fluid & 360' Gas Cut Drlg. Fluid, 30-ISIP-1838, 40-FSIP-741, FP 167-335.  
2/13/62 - TD 8120' Sd. & Shale - DST #2 7990 - 8120' - Mis-run - Hole in drill pipe - Re-set packer at 7980 - 8120', Open 2 hrs. Gas to surf. 2 hrs., Rec'd 2620' Oil & Gas Cut Drlg. fluid, FP 500 - 1210, 30-FSIP-2480.  
2/14/62 - Drlg. 8140' Lime & Sand  
2/15/62 - Drlg. 8245' Sd. and shale

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **J. C. WILLIAMSON**Address **BOX 16****MIDLAND, TEXAS**By *[Signature]*  
Supt.

Title \_\_\_\_\_