	1		Form C-103	
NO. OF COPIES RECEIVED	~		Supersedes Old	
DISTRIBUTION	-		C-102 and C-103	
SANTAFE	NEW MEXICO OIL CONSE	ERVATION COMMISSION	Effective 1-1-65	
FILE	-			
U.S.G.S.	-		5a. Indicate Type of Lease State X Fee	
LAND OFFICE				
OPERATOR			5. State Oll & Gas Lease No.	
			B-11303	
(DO NOT USE THIS FORM FOR PRO				
1.	7. Unit Agreement Name			
2. Name of Operator	8. Farm or Lease Name			
Humble Oil & Refin	New Mexico State BM			
3. Address of Operator			9. Well No.	
P. O. Box 2100, Hobbs, New Mexico 88240			3	
			10. Field and Pool, or Wildcat	
4. Location of well UNIT LETTER _ P, 990 FEET FROM THE South 1NE AND 990 330 FEET FROM			North Justis Fusselman	
THE East LINE, SECTION 2 TOWNSHIP 25-S RANGE 37-E NMPM.				
15. Elevation (Show whether DF, RT, GR, etc.)			12. County	
AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII			Lea	
<sup>16.</sup> Check	Appropriate Box To Indicate N		er Data	
	NTENTION TO:	-	REPORT OF:	
NOTICE OF I	NTENTION TO:	30002002111		
PENFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CEMENT JOB		
PULL OR ALTER CASING		OTHER		
OTHER	• • • • • • • •			
17, Describe Proposed or Completed O	Operations (Clearly state all pertinent deta	ils, and give pertinent dates, including	estimated date of starting any proposed	
work) SEE RULE 1103.			1	

See attached sheet.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

.

SIGNED	TITLE	Dist. Adm. Supvr.	DATE	4-6-65
APPROVED BY	TITLE		DATE	
CONDITIONS OF APPROVAL, IF ANY:				

## New Mexico State EM #3 (North Justis McKee)

- 1. Pulled tbg. and packer.
- 2. Loaded hole with 100 blls. lease crude.
- 3. Perforated 8083-8088, 8090-8094, 8103-8108, 8111-8118,

ſ

- 8131-8138, 8173-8176, 8178-8183 and 8185-8187 with one radio active jet shot per ft.
- 4. Set Cardinal select liner at 8143 by wireline.
- 5. Working on Fusselman side of well for 19 days.
- 6. Ran tbg. with packer and 1-1/2" tail pipe. Failed to get into liner with tail pipe. Pulled tbg. and orange peeled bottom jt. of 1-1/2" tbg. Went into liner 2' and stopped. Started out of hole. Weight indicates pulling liner. Pulled Cardinal liner.
- 7. Ran tbg., packer and tail pipe. Set packer at 8015 with tail pipe at 8139.
- 8. Pumped 500 gals. of BJ Jel Block agent into original production interval. Acidized with 1000 gals. 10% MCA acid with an average injection rate of 15 GPM. Max. press. 1500#. Min. press. 700#. Job by BJ Service.
- 9. Swabbed and tested. Recovered all load oil.
- 10. Put well to pumping. Tested.
- 11. Shut in well while testing. Fusselman side of well.
- Well recompleted thru old perf. 814-52, 8156-64 and new perf. 8083-8088, 8090-8094, 8103-8108, 8111-8118, 8131-8138, 8173-8176, 8178-8183 and 8185-8187. Unsuccessful.