

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Mobil Oil Corporation		5. State Oil & Gas Lease No.
3. Address of Operator Suite 800, Three Greenway Plaza East, Houston, Texas 77046		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>I</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>25-S</u> RANGE <u>37-E</u> NMPM.		8. Farm or Lease Name Smith
		9. Well No. 3
		10. Field and Pool, or Wildcat Jalmat Yates Gas
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
8/13/76

3506 TD, OH 3147-3506. MIRU Longhorn SD Unit 8/11/76, kill well w/140 - 9# br, instl BOP's, pull 94 jts, SDFN.

8/14/76

3506 TD, OH 3147-3506. WIH w/CIBP on tbg, hung up & set @ 2965, displ hole w/9.5# mud, spot 40x plug 2710-2965, hole would not fill, called RRC, prep to loc leak.

8/17/76

3506 TD, 2710 PBD. Ran pkr to 1500, test below pkr w/550 psi/ok, test above pkr 500 psi/ok, pkr hung up @ 1280, talk w/RRC, ok to load hole w/9.5# mud laden fluid & spot 75x C plug 855-1300, 20x 0-90, unable to pull 7" valve, ok from commission to instl monument, rel Longhorn unit 4 PM 8/16/76, P&A 8/16/76.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Runyan

TITLE Authorized Agent

DATE 8-23-76

APPROVED BY John W. Runyan

TITLE Geologist

DATE SEP 11 1976

CONDITIONS OF APPROVAL, IF ANY: