

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Las Cruces**  
Lease No. **055546**  
Unit **E. J. Wells**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<b>X</b>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**April 17,** 19 **47**

Well No. **13** is located **1980** ft. from **N** line and **660** ft. from **E** line of sec. **5**  
**C NW 1/4, Section 5** **253** **37E** **N.M.P.M.**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Langlie-Mattix** **Lea** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3216** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**T.D. 3526'. Well was shot from 3485' to 3526' with 100 qts. L.N.G. Tamped with 30' sand and 60' pea gravel. Hole was loaded with oil. After cleaning out to 3526', tubing was landed at 3513'. At end of 30 hour snub test well averaged 1.25 BOPM.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **ANDERSON-PRICHARD OIL CORPORATION**

Address **Box 1697,**  
**Hobbs, New Mexico.**

By *J. E. Cline*  
Title **District Clerk**