


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 0555 46



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 21, 1947

Well No. 13 is located 1980 ft. from [N] line and 660 ft. from [E] line of sec. 5

C NW 1/4 SW 1/4 Sec. 5 25-S 37-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Langlie Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3216 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 3375' Set 5 1/2" O.D. 14# H40 seamless casing at 3369' with 500 sacks common cement on March 17, 1947, at 3.30 A.M. Operations to test casing began 3-19-47 at 8 A.M. Casing was tested with 1000# pressure for 30 minutes. Pressure decreased 30#. After drilling plug at end of 72 hours, cement was tested for 30 minutes with 1000# pressure. Pressure decreased 40#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ANDERSON-PRITCHARD OIL CORPORATION

Address Box 1697

Hobbs

New Mexico.

By [Signature]

Title District Clerk