



*State Office*  
(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau 42-R358.3.  
Approval expires 12-31-55.  
**Las Cruces**

Land Office \_\_\_\_\_  
Lease No. **055546**  
Unit **Wells**

**RO-770 SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**January 5, 1956**, 19\_\_

Well No. **3** is located **1980** ft. from **NIX** line and **1980** ft. from **IX** line of sec. **5**  
**C-NE/4 SW/4 Sec. 5** **25S** **37E** **NMPM**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Langlie-Mattix** **Lea** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3218.5** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**cement circulated to surface.**

Ran 253' of 9-5/8" 32# casing using 225 sacks of cement. ^  
 Waited 24 hours. Pressured up with 800#. Held 30 minutes. No leaks.

**RECEIVED**

**JAN 10 1956**  
**LAND OFFICE**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **R. OLSEN**  
 Address **2811 Liberty Bank Bldg.**  
**Oklahoma City, Okla.**  
**Drawer "Z", Jal, New Mexico**

By *R. Olsen*  
 Title *Mr. Monroe Cummings*